

From: (b)(6) Mr CIV USAF USCENTCOM CCHC/F
Sent: Friday, January 21, 2011 7:45 AM
To: (b)(6) Mr CIV USAF USCENTCOM CCHC-F; (b)(6) CTR
USCE -F; (b)(6) @eaton.com'; (b)(6)
USAF AFMC OO-ALC/GHSBD'; (b)(6) CDR MIL USN
USCENTCOM CCJ4-E
Cc: (b)(6) Mr CIV USAF USCENTCOM CCHC-F; (b)(6)
Mr CIV USAF USCENTCOM CCHC-A; (b)(6) Mr CIV
SCENTCOM CCJ6-E
Subject: RE: Water Leak in UPS Room - Damage to UPS?

By the way, this is in Bldg 570, new HQ under construction, , not 540.

From: (b)(6) Mr CIV USAF USCENTCOM CCHC/F
Sent: Friday, January 21, 2011 7:40 AM
To: (b)(6) CTR USCENTCOM CCHC/F; (b)(6) @eaton.com; ' (b)(6) Civ USAF
AFMC OO-ALC/GHSBD'
Cc: (b)(6) Mr CIV USAF USCENTCOM CCHC/F; (b)(6) Mr CIV USAF
USCENTCOM CCHC/A; (b)(6) Mr CIV USAF USCENTCOM CCJ6/MP
Subject: Water Leak in UPS Room - Damage to UPS?
Importance: High

A condensate line apparently broke on one of the CRAC Units, in the UPS Room, causing condensate to collect and drain to the UPS switch gear below. Additionally, under-floor systems in the room may have sustained extensive wetting.

(b)(6) we need an Eaton Rep here ASAP to assess damage.

With the light of day, 6CES is cutting power to the building.

(b)(6) DAF, YF02
Chief of Facilities (CCHC-FO)
Headquarters' Commandant
US Central Command
7115 South Boundary Blvd
101

(b)(6)