

From: (b)(6) COL MIL USA USCENTCOM CCJ4/E
To: Anderson, Scott M DV6 CIV USAF USCENTCOM CCJ4/AD
Cc: (b)(6) Col MIL USMC USCENTCOM CCJ4/ACS; (b)(6) Mr CIV USAF USCENTCOM CCJ4/E;
(b)(6) LTC MIL USA USCENTCOM CCJ4/E; (b)(6) CDR MIL USN USCENTCOM
Subject: RE: Leak Part 2
Date: Friday, January 21, 2011 8:21:37 AM

Sir,

We had a water leak in a condensate line in one of the CRAC units in the UPS room. The water possibly affected some of the underfloor bus duct in the UPS room. Eaton will return and check out their gear.

The water also dripped down onto one of the UPS Switchboards on the first floor. The Contractor deenergized the front of the switchboard and has opened the cabinets and has been ventilating the unit. They are in the process of deenergizing the power to the switchboard (must be done at the transformer) and then will get into the back of the unit (where power is fed to) to see if any water got in there. Aneco will then be able to determine what corrective action is required. I will keep you informed as I get updates.

Vr

(b)(6)

From: (b)(6) COL MIL USA USCENTCOM CCJ4/E
Sent: Friday, January 21, 2011 8:13 AM
To: Anderson, Scott M DV6 CIV USAF USCENTCOM CCJ4/AD
Cc: (b)(6) Col MIL USMC USCENTCOM CCJ4/ACS
Sub

We have an initial report of an additional leak in the building caused by a broken water line to an air handling unit. Assessment is ongoing – we will update as soon as possible.

Vr

(b)(6)