[redacted]

Recovered Bullets – ETT Compound

FOB Robinson

Bullets in custody of KAF CID Photographed at CID office 9 Apr 06

MAJ (b)(6); (7)(

Overall Classification: ~~SECRET~~ REL US/CAN

[redacted]

Bullet 1 “Side A”: recovered from South side of the wall on the ETT rooftop, at approximately the same height as CPT [redacted] hip GSW

Characteristics:

- .30 caliber round
- Copper jacketed
- Core missing
- Aluminum base cup

Characteristics indicative of 7.62x51mm NATO AP round

Bullet 1 "Side B": recovered from South side of the wall on the ETT rooftop, at approximately the same height as CPT (b)(6); (7)(c) hip GSW



Characteristics:

- Steel tip insert intact, folded over
- Indication of black tip

Characteristics indicative of 7.62x51mm NATO AP round

Bullet 2 “Side A”: recovered from South side of the wall around the ETT compound, near tent

Characteristics indicative of 7.62x51mm NATO AP round

Characteristics:

- .30 caliber round
- Steel core
- Copper jacketed
- Aluminum base cup
- Tip insert intact

Bullet 2 “Side B”: recovered from South side of the wall around the ETT compound, near tent



Characteristics:

•Tip insert intact

Characteristics indicative of 7.62x51mm NATO AP round


Approx. 7.62mm
26
25
9
10
11
23
24
25
26
27
28