

From: (b)(6) MSG MIL USA USCENTCOM CCHC/PMO
Sent: 14, 2010 5:37 PM
To:
Cc: (b)(6) Mr CIV USAF USCENTCOM CCHC/F; (b)(6) CTR
USCE F; (b)(6) Mr CIV USA M
CCHC/SE
Subject: Serious Injury at the new CENTCOM Bldg 570
Attachments: photo.JPG

ALCON,
Information is limited at this time due to the individual being in critical condition and was transported to Tampa General at 1705 hours.

At aprox. 1442 hours, (b)(6), who works for Clark Construction fell off the top of the roof and/or crane and struck the ground below. There were several large lacerations and opened fractures on his head, arms and knees, though was conscious at the time when transported by ambulance to Tampa General.

Project Manager: Mr. (b)(6)
Supervisor: Mr. (b)(6)

A review of the CENTCOM security cameras does show this occurrence from a distance

v/r
MSG (b)(6)
Antiterrorism/Force Protection

(b)(6)