

Spill Response Summary

15 Apr 2010

- Mr. (b)(6) received notification from Mr. (b)(6) at approximately 0950, Thursday 15 Apr 2010 that a piece of construction equipment on Zemke Avenue was leaking fluid
- Mr. (b)(6) and Mr. (b)(6) arrived on scene at approximately 0955, contractor was in the process of applying absorbent – Mr. (b)(6) and Mr. (b)(6) used spill response absorbent pads and assisted the contractor in cleaning up the spill
- Contractor was Ogeechee Steel Company working at the new CENTCOM building construction site; the equipment was a Genie Hi-Lift vehicle; Incident involved approximately 2 – 3 gallons of hydraulic fluid on the asphalt roadway due to a broken hydraulic line on the Genie hi-lift
- Mr. (b)(6) and Mr. (b)(6) collected the absorbent materials and will process through the HazWaste 90-day facility for proper disposal
- No negative environmental impact – roadway stain remains
- Not a reportable incident